



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION VIII
999 18th STREET - SUITE 500
DENVER, COLORADO 80202-2405



03632VIC-V

CLASS V FIELD INSPECTION REPORT

COMPANY: Public Service Co. of Colorado
REPRESENTATIVE: See attached list
ADDRESS: 2701 W. 7th Ave. PHONE: _____
CITY/STATE/ZIP: Denver, CO 80204

RECORDS REVIEW

1) Previous Inspection Dates: none
2) _____

SITE INSPECTION

DATE: 10-5-89 Time: 1:00 (am/pm)
Inspection Type: Routine (Routine, Compliance, Enforcement)
Well Type: 5X26 Status: Active No. Wells: 1
Well Type: _____ Status: _____ No. Wells: _____
Well Type: _____ Status: _____ No. Wells: _____

General Site Condition: good

Photos? ☒ (Y) ☐ (N) See photo log and attached photos

Fluid Sample Needed? (Y) ☒ (N) Sample Taken? (Y) ☒ (N)
Follow Up Inspection Needed? (Y) ☒ (N)

Comments: Well organized site

INSPECTOR(S): Victoria Parker-Christensen Arnold J. Boettcher

NOTICE OF INSPECTION



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION VIII, 999 18TH STREET - SUITE 500
DENVER, COLORADO 80202-2405

Date: Oct 5, 89

Notice of inspection is hereby given according to Section 1445(b) of the Safe Drinking Water Act (42 U.S.C. §300f et seq.).

Hour: 1:00p. 4

Firm Name: Public Service Company of Colorado

Firm Address: 2701 West 7th Avenue, Denver, CO 80204

REASON FOR INSPECTION:




For the purpose of inspecting records, files, papers, processes, controls and facilities, and obtaining samples to determine whether the person subject to an applicable underground injection control program has acted or is acting in compliance with the Safe Drinking Water Act and any applicable condition of permit or rule authorization.

SECTION 1445(b) of the SAFE DRINKING WATER ACT is quoted below:

Section 1445(b)(1): Except as provided in Paragraph (2), the Administrator, or representatives of the Administrator duly designated by him, upon presenting appropriate credentials, and a written notice to any supplier of water or other person subject to (a), or person subject (A) a national primary drinking water regulation prescribed under Section 1412(B) an applicable Underground Injection Control Program, or (C) any requirement to monitor an unregulated contaminant pursuant to subsection (a), or person in charge of any of the property of such supplier or other person referred to in clause (A), (B), or (C), is authorized to enter any establishment, ... facility, or other property of such supplier or other person in order to determine whether such supplier or other person has acted or is acting in compliance with this title, including for this purpose, inspection, at reasonable times, of records, files, papers, processes, controls, and facilities, or in order to test any feature of a public water system, including its raw water source. The Administrator or the Comptroller General (or any representative designated by either) shall have access for the purpose of audit and examination to any records, reports, or information of a grantee which are required to be maintained under subsection (a) or which are pertinent to any financial assistance under this title.

Amelia B. Bratcher, Hydrologist
Inspector's Name & Title (Print)

Victoria Parker Christensen
Inspector's Signature
Env. Engineer



2147E 32-86

ABCHIAIT PBEZEKLEB2
BUT LIT

PHOTO PLASTIC PRODUCTS, INC. P.O. BOX 903838 ORLANDO, FL 32890-3838 • (302) 889-3100

COS5000-1947 October 5, 1989

Groundwater Technology, Inc.

Temporary Infiltration Gallery, 2701 W 7th Ave

Public Service of Colorado Denver, CO

Old drain, pt of contamination; located under
stairs is plugged.

#19

COS5000-1947 October 5, 1989

Groundwater Technology, Inc.

Temporary Infiltration Gallery

Public Service of Colorado, 2701 W 7th Ave
Denver, CO

Hydrogen Peroxide injection

#17

COS5000-1947 October 5, 1989

Groundwater Technology, Inc.

Temporary Infiltration Gallery, 2701 W 7th Ave

Public Service of Colorado Denver, CO

Over View ing System H_2O_2 and Nutrients

#18

COS5000-1947 October 5, 1989

Groundwater Technology, Inc.

Temporary Infiltration Gallery 2701 W 7th Ave

Public Service of Colorado Denver, CO

plumbing associated with ReInjection

20% water treated with Nutrients

80% straight water

#16

Print F
ARCHIVAL PRESE

STYLE 35-8

COS5000-1947




October 5, 1989

Groundwater Technology, Inc.

Temporary Infiltration Gallery

Public Service of Colorado

PHOTO PLASTIC PRODUCTS, INC. P.O. BOX 607638 ORLANDO, FL 32860-7638 • (305) 886-3100



COS5000-1947 October 5, 1989
Groundwater Technology, Inc.
Temporary Infiltration Gallery
Public Service of Colorado 2701

Public Service of Colorado
1/3 HP Submersible pump at Recovery Well
and water meter

ry
2701 W 7th Ave
Denver, CO

#12

COS5000-1947 October 5, 1989
Groundwater Technology, Inc.
Temporary Infiltration Gallery
Public Service of Colorado 2701

2701 W 7th Ave, Denver

Die Stripper

#13

COS5000-1947 October 5, 1989
Groundwater Technology, Inc.
Temporary Infiltration Gallery
Public Service of Colorado 7701

2701 W 7th Ave

Denver, Co

Activated Carbon filters


#14

COS5000-1947 October 5, 1989
Groundwater Technology, Inc.
Temporary Infiltration Gallery
Public Service of Colorado. 2701

illery
o, 2701 W 7th ave
Denver, CO

Nutrient tank

#15



COS5000-1947 October 5, 1989
Groundwater Technology, Inc.
Temporary Infiltration Gallery, 2701 W 7th Ave
Public Service of Colorado Denver, CO

VR (person) standing at SW corner of
water gallery

#20

COS5000-1947 October 5, 1989
Groundwater Technology, Inc.
Temporary Infiltration Gallery, 2701 W 7th Ave
Public Service of Colorado Denver, CO

Over view of Inj facility from SW corner

#21

COS5000-1947 October 5, 1989
Groundwater Technology, Inc.
Temporary Infiltration Gallery, 2701 W 7th Ave
Public Service of Colorado

View Inj facility from NW Corner - barrels
contain withdrawn H₂O no treatment #22